From:

Steve Demczak

To:

Angela Nance; Oakley, Dennis; Suzanne Steab 7/22/2010 8:02 AM

Date:

Subject:

June Insp.

Attachments: 20100722081909.pdf



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

GAYLE F. McKEACHNIE
Lieutenant Governor

Representativ	es Present During the Inspection:
Company	Dennis Oakley
OGM	Steve Demczak
OGM	Karl Houskeeper

# **Inspection Report**

Permit Number:	C0150017		
Inspection Type:	PARTIAL		
Inspection Date:	Monday, June 14, 2010		
Start Date/Time:	6/14/2010 10:00:00 AM		
End Date/Time:	6/14/2010 11:00:00 AM		
Last Inspection:	Monday, May 10, 2010		

Inspector: <u>Steve Demczak</u>, Weather: <u>Sunny</u>, 70's

InspectionID Report Number: 2396

of Operations

Accepted by: jhelfric

6/16/2010

Permitee: PACIFICORP

OLENE S. WALKER
Governor

Operator: ENERGY WEST MINING CO

Site: DES BEE DOVE MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

**Current Acreages** 

134.31	<b>Total Permitted</b>
40.90	<b>Total Disturbed</b>
43.40	Phase I
	Phase II
2.52	Phase III

Mineral	Ownership	Types
---------	-----------	-------

 ✓ Federal
 ✓ Underground

 □ State
 □ Surface

 □ County
 □ Loadout

 ✓ Fee
 □ Processing

 □ Other
 □ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violation were issued.

Inspector's Signature:

Stephy Day

Date

Tuesday, June 15, 2010

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0150017

Inspection Type: PARTIAL Inspection Date: Monday, June 14, 2010 **Inspection Continuation Sheet** 

Page 2 of 3

## REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
   For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.

  b. For PARTIAL inspections check only the elements evaluated.

  2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Eurluntad	Nist Assets state		
1.	Permits, Change, Transfer, Renewal, Sale	Evaluated	Not Applicable	Comment	Enforcemen
2.	Signs and Markers	<b>V</b>			
3.	Topsoil	<u> </u>		<u> </u>	
4.a	Hydrologic Balance: Diversions	<u> </u>		<u> </u>	
4.b			<u> </u>		
4.c		<u> </u>		<u> </u>	
4.d					
4.e					
<del></del>	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches			<del></del>	
<del></del> 7.	Coal Mine Waste, Refuse Piles, Impoundments			<u> </u>	<u> </u>
<del></del> 8.	Noncoal Waste				
<del>0.</del> 9.				<u> </u>	
	Protection of Fish, Wildlife and Related Environmental Issues				
	Slides and Other Damage	✓		<b>Y</b>	
	Contemporaneous Reclamation				
12.	Backfilling And Grading	<b>V</b>		~	
13.	Revegetation	V		<b>V</b>	
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing		<b>V</b>		
16.b	Roads: Drainage Controls		<b>V</b>	$\overline{\Box}$	
17.	Other Transportation Facilities		<u> </u>		
18.	Support Facilities, Utility Installations	<u> </u>		<u> </u>	
	AVS Check				
20.	Air Quality Permit			<del>_</del>	
	Bonding and Insurance				
	Other				

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Monday, June 14, 2010

Page 3 of 3

## 1. Permits, Change, Transfer, Renewal, Sale

There is no pending permitting action with the Division at this time.

#### 2. Signs and Markers

#### 3. Topsoil

All topsoil was used in reclamation.

### 4.a Hydrologic Balance: Diversions

Diversions were spot-checked and would function in a storm event.

# 4.c Hydrologic Balance: Other Sediment Control Measures

The mine site is pocked to control sediment control.

### 8. Noncoal Waste

The area was clear of non-coal waste material.

### 10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

### 12. Backfilling And Grading

The site is backfilled and graded.

#### 13. Revegetation

Vegetation is coming up throughout the property.

## 18. Support Facilities, Utility Installations

There are no facilities at this site.